INSPECTION REPORT

Name of Work	:	IMRPOVEMENTS TO FOOTPATH 8TH, 7TH CROSS ROADS OF 3RD MAIN ROAD, IN WARD NO 13, IN SHETTYHALLI SUB-DIVISION
Work Order	:	EE/DD/WO/339/2014-15 Date 31.3.2015
Agency	:	B UMESH
B.R No & Date	:	B.R.No:265/2015-16, Date: 30-09-2015
Bill Amount	:	Rs.14,01,803/-
Job Code	:	013-15-000009
P.Code	:	P1771
Date of Inspection	:	20-03-2017

The above said work "Improvements to Foot paths 8th, 7th Cross roads of 3rd Main road, in ward no 13, in Shettyhalli Sub Div" was Inspected by me by the Concerned Ward Engineer.

The above said work is inspected by me along with the Concerned Ward Engineer.

The work done is Satisfactory

MANJUNATH. K
DQM BE (CIVIL)
EXECUTIVE ENGINEER (RTD)
PUBLIC WORKS DEPARTMENT

Scanned by CamScanner

Name of Work:- Sketch showing the work for Improvements to foot path at 8th & 7th cross roads & 3rd main road in ward No. 13 in SSD.



MANJUNATH. K
DQM BE (CIVIL)
EXECUTIVE ENGINEER (RTD)
PUBLIC WORKS DEPARTMENT

ಸಹಾಯಕ ಕಾರ್ಯನಿರ್ವಾಹಕ ಅಭಿಯಂತರರು
ಕೆಬ್ಲ್ಯೂ ಉಪವಿಭಾಗ, ಬಾಣಸವಾಡಿ ವಲಯ
ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
ಎಸ್.ಎಂ. ರಸ್ತೆ, ರವೀಂದ್ರನಗರ, ಬೆಂಗಳೂರು

Scanned by CamScanner

Name of Work :- Improvements to Footpath 8th, 7th Cross Roads of 3rd main Road in Ward no. 13, Shettyhalli Sub-division.





MANJUNATH. K
DQM BE (CIVIL)
EXECUTIVE ENGINEER (RTD)
PUBLIC WORKS DEPARTMENT

ನಿರ್ವಾಹಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಶೆಟ್ಟಿಹಳ್ಳಿ ಉಪವಿಭಾಗ, ಬಾಣಸವಾಡಿ ವಲಯ
ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
ಎಸ್.ಎಂ. ರಸ್ತೆ, ರವೀಂದ್ರನಗರ, ಬೆಂಗಳೂರು

Scanned by CamScanner

Name of Work :- Improvements to Footpath 8th, 7th Cross Roads of 3rd main road in ward No. 13 in Shettyhalli Sub-division

Scanned by CamScanner